

## TOUCH-UP PAINT REPAIR INSTRUCTIONS

- 1) Begin by shaking the BK-01 touch up paint bottle well, then set the bottle aside upright while you are performing the next task.
- 2) Remove any loose chips/debris in the damaged area by wiping with a clean rag or fine wire brush.
- 3) If the powder coating has been compromised down to bare metal and rust has formed - you will need to remove any rust with 120 grit sand paper. Lightly sand the damaged area so that no rust appears while blending the chipped areas into the rest of the part. Clean the damaged area again and make sure it is free of all sanding grit and dust.
- 4) Apply a generous amount of BK-01 paint onto the sponge supplied with your kit and begin to dab the paint onto the damaged area. Dab the area well, but not too heavily and let dry for 5 minutes. Repeat the dabbing process at least 2-3 times if needed and leave to dry for 5 minutes between each touch up.
- 5) Let the part sit for at least 30 minutes and the touch up process is complete.

### INCLUDED IN KIT:

- 1- Cardinal BK-01 Touch-Up Paint Bottle
- 1- Sponge (Used to dab paint onto touch-up areas\*)

